Dart Aerospace Ltd. Friday, 06/03/2009 8:40:21 AM Date: Linda Lacelle User: **Process Sheet** : BRACKET ASSEMBLY Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** Job Number : 46313 **Estimate Number** : 10334 : D2804042 P.O. Number **Part Number** . D2804 REV C This Issue : 06/03/2009 S.O. No. : **Drawing Number** : NC : N/A Prsht Rev. **Project Number** First Issue : // : SMALL /MED FAB : C Type **Drawing Revision** : 44551 **Previous Run** Material Each **Due Date** : 09/03/2009 Qty: Written By Checked & Approved By Comment MS21043-3 was MS21042L3 KJ/JLM 05.03.30 Est Rev:G As per Rev C 06-11-08 JLM **Additional Product** Job Number: Seq. #: **Machine Or Operation:** Description: 1.0 D28042 Bracket Comment: Qty.: 1.0000 Each(s)/Unit Total: 4.0000 Each(s) STA 155 Bracket Pick: **Qty Part Number** Description D2804-2 **Bracket** 2.0 D28052 Comment: Qty.: 1.0000 Each(s)/Unit Total: 4.0000 Each(s) Stop Pick: **Qty Part Number** Description Batch D2805-2 1 Stop 3.0 D2809 Bushing Comment: Qty.: 1.0000 Each(s)/Unit Total: 4.0000 Each(s) Bushing Pick: Qty Part Number Description

D2809 Bushing

4.0 SMALL FAB 1

1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Press D2805-2 into arm as per Dwg D2804



## **Dart Aerospace Ltd**

Dait Aerospace Liu								
W/O:			WORK ORDER (	CHANGES			***	
DATE	STEP	PF	ROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								<u> </u>
<del></del>			,					
Part No	:	PAR #:	Fault Category:	NCR: Y	es No <b>DQ</b>	A:	_ Date: _	
	Resolution	on: <u> </u>	Disposition:	QA: N/0	Closed:		Date: _	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B			A		
DATE	STEP	Section A	Initial Action Description Chief Eng Chief Eng		Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector	

NOTE: Date & initial all entries

Date: Friday, 06/03/2009 8:40:21 AM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: BRACKET ASSEMBLY** Job Number: 46313 Part Number: D2804042 Job Number: Seq. #: **Machine Or Operation:** Description: INSPECT WORK TO CURRENT STEP 5.0 QC5 Comment: INSPECT WORK TO CURRENT STEP 6.0 POWDER COATING POWDER COATING Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 START TIME: **OVEN TEMPERATURE:** FINISH TIME: 7.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION SMALL FAB 1 SMALL & MEDIUM FAB RESOURCE 8.0 5,5 Comment: SMALL & MEDIUM FAB RESOURCE 1 Press Fit D2809 as per Dwg D2804 AN3C16A Comment: Qty.: 2.0000 Each(s)/Unit Total: 8.0000 Each(s) Bolt Pick: Qty Part Number Description 2 AN3C16A 10.0 MS210433 Nut Comment: Qty.: 2.0000 Each(s)/Unit Total: 8.0000 Each(s) Nut Pick: **Qty Part Number** Description Batch 1/0/5 MS21043-3 Nut

Form: rprocess

Page 2

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES	WORK ORDER CHANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #: *Fault Category: NC	CR: Yes	No DQA	۸:	Date: _	10.00


Resolution:		olution:	Disposition:		QA: N/C Closed:		Date:	
			WORK ORDER NON-CONFORMANCE (NCR)					
		STED Description of NC		Corrective Action Section B		Verification	Ammuoval	A
DATE	STEP	Section A	<b>Initial</b> Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
				r.				

NOTE: Date & initial all entries

Date: Friday, 06/03/2009 8:40:21 AM User: Linda Lacelle **Process Sheet** Drawing Name: BRACKET ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Job Number: 46313 Part Number: D2804042 Job Number: Seq. #: **Description: Machine Or Operation:** NAS1515H3 11.0 Washer Comment: Qty.: 4.0000 Each(s)/Unit Total: 16.0000 Each(s) Washer Pick: 4 NAS1515H3 Washer Part Number Description Batch M109268 A/R LPS-3 Corrosion Spray 12.0 SMALL FAB 1 SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 1-Spray LPS-3 on Bolt Shaft, not on thread as per Dwg D2804 2-Assemble as per Dwg D2804. 13.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 14.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock \_ Location: 15.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion



DESIGN CP CP		I	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA			
CHEC	CED //	APPROVED ,	DRAWING NO.	REV. C		
	H	*#-	D2804	SHEET 1 OF 2		
DATE			TITLE	SCALE		
06.1	0.16		STA 155 BRACKET	1:3		
Α		00.11.07	NEW ISSUE			
В	-	04.11.22	ADD CUTOUTS & -043/-044			



## D2804-1 BRACKET (SHOWN), D2804-2 BRACKET (OPPOSITE)


- 1) MACHINE PER DRAWING FILE "D2804-1C.SLDPRT"
- 2) MATERIAL: 6061-T6 (QQ-A-200/8) OR (QQ-A-250/11) 0.500 THICK
- 3) DEBURR TO LEAVE RO.030 0.063 ON ALL EDGES
- 4) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

Copyright © 2000 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



DESIGN CP	DRAWN BY		ROSPACE LTD y, ontario, canada		
CHECKED	APPROVED #	DRAWING NO.	REV. C		
- AT	#	D2804	SHEET 2 OF 2		
DATE	-	TITLE	SCALE		
06.10.16		STA 155 BRACKET	1:3		



## D2804-041/-043 BRACKET ASS'Y (SHOWN). D2804-042/-044 BRACKET ASS'Y (OPPOSITE)

6) FINISH: POWDER COAT ASSEMBLY GLOSS WHITE (4.3.5.1) OR GREY SANDTEX (4.3.5.6) OR BLACK SANDTEX (4.3.5.7) OR GREEN SANDTEX (4.3.5.8) PER DART QSI 005 4.3

Copyright © 2000 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.